

HABS
OHIO
47-0882
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to
First Church in Oberlin (Congregational)
N. Main & W. Lorain Sts.
Oberlin
Lorain County
Ohio

HABS No. OH-2117

Jack E. Boucher, Photographer, September 1971

OH-2117-3 EXTERIOR, EAST FRONT AND SOUTH SIDE
OH-2117-4 EXTERIOR, EAST FRONT FROM NORTH
OH-2117-5 EXTERIOR, EAST FRONT

HABS
OHIO
42-61265
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

FIRST CHURCH IN OBERLIN (CONGREGATIONAL)
N. Main and W. Lorain Streets
Oberlin
Lorain County
Ohio

HABS No. OH-2117

Photographs OH-2117-1 through OH-2117-5 were previously transmitted to the Library of Congress. This is Index to Photographs page 2.

Photographs by Perry E. Borchers of the Ohio State University, 1957 and 1958.

- OH-2117-6 EAST FACADE, LOWER PORTION
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-100L.
- OH-2117-7 EAST FACADE, TRIPOD TILTED UP
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-101L.
- OH-2117-8 EAST AND NORTH FACADES, ANGLED
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-102L.
- OH-2117-9 SOUTH AND WEST FACADES FROM SW
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-103L.
- OH-2117-10 SOUTH FACADE
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-104L.
- OH-2117-11 WEST FACADE, LOWER PORTION
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-105L.
- OH-2117-12 ALTAR FRONT, MAIN ROOM, LEFT HALF
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-106L.
- OH-2117-13 ALTAR FRONT, MAIN ROOM, RIGHT HALF
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-107L.

**FIRST CHURCH IN OBERLIN
(CONGREGATIONAL)**

HABS No. OH-2117

Index to Photographs (Page 3)

- OH-2117-14 BALCONY, REAR OF MAIN ROOM
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-108L.
- OH-2117-15 BALCONY, REAR OF MAIN ROOM
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-109L.
- OH-2117-16 BALCONY, MAIN ROOM, FROM SOUTH SIDE
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-110L.
- OH-2117-17 LOOKING FORWARD UNDER NORTH PORTION OF BALCONY
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-113L
- OH-2117-18 ACROSS BACK OF FIRST FLOOR, MAIN ROOM FROM SOUTH
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-115L.
- OH-2117-19 LOOKING NORTH IN ENTRANCE STAIR HALL
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-116L.
- OH-2117-20 NORTH SIDE OF RAISED PULPIT
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-117L.
- OH-2117-21 EDGE OF RAISED PULPIT
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-118L.
- OH-2117-22 ATTIC, LOOKING EAST
 Copy photograph of photogrammetric plate
 LC-HABS-GS07-T-810-119L.